




LED Spot EcoMax

| Type | CCT | kg |
|------------------|-------|--------|
| LED SP-RF-E-4.5W | 2700K | 0.08kg |
| | 4000K | 0.08kg |





| Type | A (mm) | B (mm) | C (mm) |
|------------------|--------|--------|--------|
| LED SP-RF-E-4.5W | 100 | 250 | 250 |




| Type | H (mm) | Ø (mm) | D (mm) |
|------------------|--------|--------|--------|
| LED SP-RF-E-4.5W | 35 | 68 | 78 |

①







Ø = 68 ± 2.5mm

②



Connection terminal not provided



Luminaires not suitable for covering with thermally insulating material.
Leuchten sind nicht mit thermisch isolierenden Materialien abzudecken.

In case of damage to the wire, it has to be replaced only by the manufacturer, distributor or by an expert, to avoid risks.









Caution: Any operation on LED module is forbidden while power-on.
Zur Vermeidung von Risiken müssen defekte Leitungen ausschließlich vom Hersteller, Inverkehrbringer oder Fachmann ausgetauscht werden.

Achtung: In Betrieb ist keine Arbeit am LED-Modul erlaubt.



The light source of this luminaire is not replaceable; when the light source reaches its end of life the whole luminaire shall be replaced.



Suzhou Opplé Lighting Co., Ltd.
215200
East Side, Fenyang Road,
Fenhu Economic Development Zone,
Wujiang City, Jiangsu Province,
P.R.China

OPPLE Lighting B.V.
Materiaalweg 6-6A
5681 RJ Best
The Netherlands
service@opple.com
www.opple.com